

Work Order ID 141722

Wednesday, February 10, 2016 10:55:38 AM

141722

Page 1

Item ID: D412-711-021

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 2/17/2016 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: MCS Date: FEB 10 2016 Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start ***NR1***
Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D412-711	K								
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefiles and create labels per PPP D412-711-021 CHG002								
120	Pick Kit	0.00							
120	Purchasing								
Packaging	Memo	0.00							
Packaging									
130	QC4- 100% Inspect kits for completeness	0.00							
130									
QC	Memo	0.00							
Quality Control									

MCS 16-03-03

DAS
28
9-89

MAR 07 2016

DAS
6
9-89

MAR 03 2016

MAR 07 2016

DAS
28
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval	
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
		OTHER : ☐							

Work Order ID 141722

Wednesday, February 10, 2016 10:55:38 AM

141722

Page 2

Item ID: D412-711-021

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 2/17/2016 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start ***NR1***Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
150		0.00							
150									
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D412-711-021								
	Location: _____								
	PPP rev: _____								
160	QC21- Final Inspection - Work Order Release	0.00							
160									
QC	Memo	0.00							
Quality Control									

1 DAS 28 9-88 MAR 07 2016

MCS MAR 07 2016

MCS MAR 07 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QS1042) Approval	
Description Work Order Deviation		Disposition		Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Picklist Print

Wednesday, February 10, 2016 10:55:43 AM

Page 1

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:A 11.04.07 new issue DD verf:EC
14.04.25 ECN14-548 DD verf:JLM

IPP Rev:B

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4324-011		Manufactured	No				Each	0.0000		1			
D4324-011									**	141327			SP
Armrest Assembly													DAS 27 9-89
D412-761-043		Manufactured	No			120	Each	0.0000	1	1			
D412-761-043									**	142246		DAS 6 9-89	SP
Modified Latch Mechanism, LH													
D412-711-101		Manufactured	No			120	Each	1.0000	1	1			
D412-711-101									**	141259			SP
Replacement Vertical Reference Window													DAS 27 9-89
					<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>						
					FG100	1							
					138985	1							
D3802-1-120		Manufactured	No			120	Each	0.0000	1	1			
D3802-1-120									**	141730		DAS 6 9-89	SP
Window Seal - 120"													
D4165-1		Manufactured	No			120	Each	3.0000	1	1			
D4165-1									**			DAS 6 9-89	SP
Doubler													
					<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>						
					ST236	3							
					115110	1							
					137259	2							

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong				
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions				
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance				
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect				
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing				
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved				
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing				
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Mislabeled	☐ Finish				
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread				
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence				
Past Expiry Date ☐	☐ Manufacturing Process	OTHER : _____							
Misidentified ☐	☐ Past Due								

Picklist Print

Wednesday, February 10, 2016 10:55:43 AM

Page 2

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

D4165-3

Manufactured No

120

Each

2.0000

1

1

D4165-3

Inner Door Panel

DAS
28
9-89

**

Location

Loc Qty

Loc Code

st238

2

137298

2

D4165-5

Manufactured No

120

Each

3.0000

1

1

D4165-5

Aft Rib

DAS
28
9-89

**

Location

Loc Qty

Loc Code

ST234

3

136737

3

D4165-7

Manufactured No

120

Each

15.0000

1

1

D4165-7

Fwd Rib

DAS
28
9-89

**

Location

Loc Qty

Loc Code

ST246

15

114255

4

116604

11

D4165-9

Manufactured No

120

Each

7.0000

1

1

D4165-9

Angle

DAS
28
9-89

**

Location

Loc Qty

Loc Code

ST237

7

119607

7

DAS

6

9-89

DAS

27

9-89

MAR 03 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐			
Design ☐	☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐			
Doc/Data ☐	☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐			
Equip/Tooling ☐	☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐			
Handling/Pre ☐	☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐			
Material ☐	☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐			
Internal Transport ☐	☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐			
Tribal Knowledge ☐	☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐			
LOA ☐	☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐			
Substation ☐	☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐			
Past Expiry Date ☐	☐	Manufacturing Process ☐	OTHER :						
Misidentified ☐	☐	Past Due ☐							

Picklist Print

Wednesday, February 10, 2016 10:55:43 AM

Page 3

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

D4165-11 Manufactured No

120 Each 2.0000 1 1

D4165-11

Door Cover Panel

DAS
28
9-89

Location

Loc Qty

Loc Code

st238

2

125784

2

120 Each 2.0000 1 1

D4207-1 Manufactured No

D4207-1

Window Retainer

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

2

137243

2

120 Each 0.0000 1 1

D4207-3 Manufactured No

D4207-3

Instrument Window

DAS
28
9-89

D4269-1

Manufactured No

120 Each 3.0000 1 1

D4269-1

Angle

DAS
28
9-89

Location

Loc Qty

Loc Code

ST089

3

123643

1

137127

2

120 Each 2.0000 1 1

D4269-3 Manufactured No

D4269-3

Angle

DAS
28
9-89

Location

Loc Qty

Loc Code

ST089

2

137270

2

DAS
6
9-89

DAS
6
9-89

MAR 04 2016

DAS
6
9-89

DAS
6
9-89

DAS
6
9-89

MAR 03 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Wednesday, February 10, 2016 10:55:43 AM

Page 4

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

D4269-5

Manufactured No

120

Each

3.0000

1

1

D4269-5

Angle

DAS
28
9-89

**

DAS
6
9-89
27
9-89

Location

Loc Qty

Loc Code

ST237

3

134700

3

D4269-7

Manufactured No

120

Each

6.0000

1

1

D4269-7

Angle

DAS
28
9-89

**

DAS
6
9-89
27
9-89

Location

Loc Qty

Loc Code

ST237

6

132994

6

D4327-1

Manufactured No

120

Each

2.0000

1

1

D4327-1

Angle

DAS
28
9-89

**

DAS
6
9-89
27
9-89

Location

Loc Qty

Loc Code

ST237

2

123687

2

D4327-3

Manufactured No

120

Each

2.0000

1

1

D4327-3

Angle

DAS
28
9-89

**

DAS
6
9-89
27
9-89

Location

Loc Qty

Loc Code

ST237

2

117081

2

D4385-1

Manufactured No

120

Each

9.0000

2

2

D4385-1

Placard

DAS
28
9-89

**

DAS
6
9-89
27
9-89

Location

Loc Qty

Loc Code

ST095

9

136305

9

MAR 03 2016

Wednesday, February 10, 2016 10:55:43 AM

Shop Packet Print

Page 4

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐ _____							

Picklist Print

Wednesday, February 10, 2016 10:55:43 AM

Page 5

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

AN3-3A Purchased No 120 Each 199.0000 22 22

AN3-3A

Bolt

DAS
28
9-89

Location

Loc Qty

Loc Code

ST350

199

m131624

99

m134034

100

22

DAS
6
9-89

DAS
27
9-89

AN3-4A Purchased No 120 Each 306.0000 20 20

AN3-4A

Bolt

DAS
28
9-89

Location

Loc Qty

Loc Code

over003

250

m133990

250

ST350

56

m129682

10

m133694

46

20

DAS
6
9-89

DAS
27
9-89

AN3-6A Purchased No 120 Each 393.0000 26 26

AN3-6A

Bolt

DAS
28
9-89

Location

Loc Qty

Loc Code

over003

300

M133932

125

M134055

175

ST349

93

M133561

93

26

DAS
6
9-89

DAS
27
9-89

MAR 03 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause			FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date	☐	Manufacturing Process	☐	OTHER :						
Misidentified	☐	Past Due	☐							

Picklist Print

Wednesday, February 10, 2016 10:55:43 AM

Page 6

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

AN3-12A

Purchased

No

120

Each

77.0000

1

1

AN3-12A

Bolt

**

DAS 27 9-89
6 9-89

DAS 28 9-89

Location

Loc Qty

Loc Code

GA

2

m129682

2

ST349

75

m133064

16

m133234

59

NAS1149F0332P

Purchased

No

120

Each

3,321.000

92

92

NAS1149F0332P

Washer

**

DAS 27 9-89
6 9-89

DAS 28 9-89

Location

Loc Qty

Loc Code

GA

384

m133709

384

ST260a

1500

m134134

1500

ST262

1437

m133938

7

m134055

1430

CR3242-4-2

Purchased

No

120

Each

81.0000

34

34

CR3242-4-2

RIVET

**

DAS 27 9-89
6 9-89

DAS 28 9-89

Location

Loc Qty

Loc Code

ST317

81

m133077

81

Wednesday, February 10, 2016 10:55:43 AM

Shop Packet Print

Page 6

MAR 03 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only. ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : ☐			

Picklist Print

Wednesday, February 10, 2016 10:55:43 AM

Page 7

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

MS20426AD3-3

Purchased

No

120

Each

4,336.000

135

135

MS20426AD3-3

RIVET

DAS
6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

1618

M131624

1618

ST312

2718

M131624

2718

130

MS20426AD4-3

Purchased

No

120

Each

2,696.000

140

140

MS20426AD4-3

Rivet

DAS
6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

1176

113064

176

m125807

1000

ST312

1520

m125807

1520

140

MS20470AD3-3

Purchased

No

120

Each

6,479.000

25

25

MS20470AD3-3

RIVET, UNIVERSAL HEAD

DAS
6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

909

1065

909

ST310

5570

16941

5570

25

MAR 03 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval	
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
		OTHER : ☐							

Picklist Print

Wednesday, February 10, 2016 10:55:43 AM

Page 8

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

MS20470AD4-3

Purchased

No

120

Each

1,340.000

90

90

MS20470AD4-3

Rivet - Universal Head

**

DAS 6 27 9-89

Location

Loc Qty

Loc Code

GA

773

2193

773

ST310

567

2193

567

MS21042L3

Purchased

No

120

Each

2,211.000

24

24

MS21042L3

Nut

**

DAS 6 27 9-89

Location

Loc Qty

Loc Code

FP001

163

m133790

163

GA

162

m133790

162

ST304

1886

m134039

1886

DAS 28 9-89

MAR 03 2016

24

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Picklist Print

Wednesday, February 10, 2016 10:55:44 AM

Page 9

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

MS21059L3

Purchased

No

120

Each

166.0000

4

4

MS21059L3

Nut Plate

DAS 6 9-89
DAS 27 9-89

DAS 28 9-89

Location

Loc Qty

Loc Code

CA

8

M129682

8

GA

50

M133990

50

ST301

77

M133363

27

M134055

50

ST303

31

M131616

5

M133016

26

1
2

MS21069L3

Purchased

No

120

Each

124.0000

34

34

MS21069L3

ANCHOR NUT

DAS 6 9-89
DAS 27 9-89

DAS 28 9-89

Location

Loc Qty

Loc Code

ST299

106

m133019

1

m133127

5

m133790

25

m133990

75

ST301

18

m131618

18

34

MS21069L08

Purchased

No

120

Each

614.0000

8

8

MS21069L08

ANCHOR NUT

DAS 6 9-89
DAS 27 9-89

DAS 28 9-89

Location

Loc Qty

Loc Code

ST299

614

123522

614

8

DAS 6 9-89
DAS 27 9-89

Wednesday, February 10, 2016 10:55:44 AM

Shop Packet Print

Page 9

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval																																																									
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : ☐			
Misidentified ☐	Past Due ☐																																																																

Picklist Print

Wednesday, February 10, 2016 10:55:44 AM

Page 10

Work Order ID: 141722

141722

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016

Required Date: 2/17/2016

Start Qty: 1.00

Required Qty: 1.00

MS21071L3

Purchased

No

120

Each

218.0000

3

3

MS21071L3

ANCHOR NUT

DAS
6
9-89
DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST299

118

124291

14

MT29702

104

ST301

100

125654

100

MS21071L08

Purchased

No

120

Each

162.0000

1

1

MS21071L08

ANCHOR NUT

DAS
6
9-89
DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST299

162

102587

62

103447

100

MAR 11 2 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Work Order ID 141722

Wednesday, February 10, 2016 10:55:38 AM

141722

Page 1

Item ID: D412-711-021

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Vertical Reference Door Modification LH

Start Date: 2/10/2016 Start Qty: 1.00 ***1***

Required Date: 2/17/2016 Req'd Qty: 1.00 ***1***

Cust Item ID:

Reference:

Customer:

Approvals: Process Plan: MCS Date: FEB 10 2016 Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start ***NR1***
Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D412-711	K								

100

Document Control
DOCUMENT CONTROL

0.00

100

DC

Memo 0.00

Doc.Control -USB or Paperwork

Photocopy bluefiles and create labels per PPP D412-711-021 CHG002

MCS MAR 03 2016

120

Pick Kit 0.00

120

Purchasing

Packaging

Memo 0.00

Packaging

MAR 03 2016

130

QC4- 100% Inspect kits for completeness 0.00

130

QC

Memo 0.00

Quality Control

REFERENCE ONLY

DAS
28
8-09

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	QTY -043	PART NUMBER	DESCRIPTION
X								D412-711-011	VERTICAL REFERENCE DOOR INSTALLATION, 212/412
	X							D205-711-013	VERTICAL REFERENCE DOOR INSTALLATION, 205/210
		X						D204-711-015	VERTICAL REFERENCE DOOR INSTALLATION, 204
			X					D214-711-017	VERTICAL REFERENCE DOOR INSTALLATION, 214
				X				D212-711-019	VERTICAL REFERENCE DOOR EAGLE SINGLE
					X			D412-711-021	VERTICAL REFERENCE DOOR KIT
A1	A1	A1	A1	A1		X		D412-711-041	VERTICAL REFERENCE DOOR ASSEMBLY
							X	D412-711-043	SNAP VENT KIT
					1	1		D412-761-043	MODIFIED LATCH MECHANISM KIT, LH (REPLACES EA20469-23/-24/-25)
					1	1		D412-711-101	REPLACEMENT WINDOW (REPLACES EAGLE P/N EB212-100L / EA20469-3)
					1	1		D3802-1-120	RUBBER STRIP
							2	D3932-1	SNAP VENT
					1	1		D4165-1	DOUBLER
					1	1		D4165-3	DOOR INNER SKIN (REPLACES EA20469-18)
					<i>W</i>	1		* D4165-5	AFT RIB (REPLACES EA20469-34)
					<i>F</i>	1		** D4165-7	FWD RIB (REPLACES EA20469-31)
					1	1		D4165-9	ANGLE (REPLACES EA20469-17)
					1	1		D4165-11	DOOR COVER PANEL (REPLACES EA20469-21)
					1	1		D4207-1	WINDOW RETAINER (REPLACES EA20469 -14)
					1	1		D4207-3	WINDOW (REPLACES EA20469-13)
					1	1		* D4269-1	ANGLE (REPLACES EA20469-33)
					1	1		** D4269-3	ANGLE (REPLACES EA20469-30)
					1	1		** D4269-5	ANGLE (REPLACES EA20469-29)
					1	1		* D4269-7	ANGLE (REPLACES EA20469-32)
					1	1		D4324-011	ARM REST ASSEMBLY (REPLACES EA20469-16)
					1	1		D4327-1	ANGLE (REPLACES EA20469-11)
					1	1		D4327-3	ANGLE (REPLACES EA20469-07)
					2	2		D4385-1	PLACARD

K

K

* PART OF EA20469-10 REAR RIB ASSEMBLY
 ** PART OF EA20469-12 FWD RIB ASSEMBLY

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	DC	DRAWING NO.	REV. K
MFG. APPR.	JLM	D412-711	SHEET 2 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	VERTICAL REFERENCE DOOR	NTS
DATE	14.04.07	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

DAS
28
9-89

REFERENCE ONLY

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	PART NUMBER	DESCRIPTION
					22	22	AN3-3A	BOLT
					20	20	AN3-4A	BOLT
					26	26	AN3-6A	BOLT
					1	1	AN3-12A	BOLT
					92	92	NAS1149F0332P	WASHER (OR AN960-10L)
					34	34	CR3242-4-2	RIVET
					135	135	MS20426AD3-3	RIVET
					140	140	MS20426AD4-3	RIVET
					25	25	MS20470AD3-3	RIVET
					90	90	MS20470AD4-3	RIVET
					24	24	MS21042L3	NUT
					4	4	MS21059L3	NUT PLATE
					34	34	MS21069L3	NUT PLATE
					8	8	MS21069L08	NUT PLATE
					3	3	MS21071L3	NUT PLATE
					1	1	MS21071L08	NUT PLATE
						1	204-030-853-125	LH COPILOT DOOR (204-030-853-137/-155)
1							D412-711-111	WIRING HARNESS, 212/412
B ₁							B ^D 4268-043	INSTRUMENT PANEL, 212/412 (REPLACES EA20469-15-412)
	1						D205-711-113	WIRING HARNESS, 205
	B ₁						B ^D 4268-041	INSTRUMENT PANEL, 205 (REPLACES EA20469-15-205)
		1					D204-711-115	WIRING HARNESS, 204
		B ₁					B ^E A20469-15-204	INSTRUMENT PANEL, 204
			1				D214-711-117	WIRING HARNESS, 214
			B ₁				B ^E A20469-15-214	INSTRUMENT PANEL, 214
				1			D212-711-119	WIRING HARNESS, EAGLE SINGLE
				B ₁			B ^D 4268-047	INSTRUMENT PANEL, EAGLE SINGLE

△K

- (A) IF CUSTOMER PREFERS TO SUPPLY AND MODIFY THEIR OWN DOOR, D412-711-021 SHOULD BE SUPPLIED IN LIEU OF D412-711-041
(B) INSTRUMENT PANEL INCLUDED WITH HARNESS ABOVE

△K

NOTES

1) WIRING HARNESSES:

For Bell 204/205/210/214 Wiring Harnesses, use drawing D2046904.
For Bell 212 Wiring Harnesses, use drawing D2046903*.
For Bell 412 Wiring Harnesses, use drawing D412-711-901.
For Bell 212 modified per SH07-28/SR02831NY use D212-761-224
or D212-761-225 depending on aircraft s/n.
* Despite the note on the drawing, D2046903 is applicable to all 212 aircraft
serial numbers

Wiring Harnesses will vary
depending on aircraft s/n.

2) D412-711-101 REPLACEMENT WINDOW:

To increase downward viewing clarity, it is acceptable to cut a small section from the replacement window on its downward side per Figure 1 of this document. The cutout can be a maximum of 9.00" wide x 17.00" long (229mm x 432mm), measured along the profile of the replacement window. The corners of the cutout must have a minimum radius of 2" (50mm). The cutout should be located at least 1.0" (25mm) from the flange. The actual shape of the cutout can vary as desired, as long as the overall dimensions are within the specified limits. See Figure 1 for reference.

3) D412-711-043 SNAP VENT KIT:

It is acceptable to install a total of up to 2X D3932-1 Snap Vents (available from Dart) onto the D412-711-101 Replacement Window to provide ventilation into the cabin. Refer to Figure 1 for acceptable locations and size of cutouts.

4) It is acceptable to use MS21042L3 nuts to install the window in lieu of anchor nuts shown on D2046901.

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	DC	DRAWING NO.	REV. K
MFG. APPR.	JLM	D412-711	SHEET 3 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	VERTICAL REFERENCE DOOR	NTS
DATE	14.04.07	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	